

To

The President,
Starlit International School,
Village Dandlawar, Tehsil Raipur Rani
Distt. Panchkula

Memo No.

4039

Dated:

1/12/17

Subject:- Certificate of Building safety in respect of School Building at village Dandlawar, Tehsil Raipur Rani in Distt. Panchkula

Ref:-

Your application dated 24.11.2017 on the above noted subject.

In this connection it is intimated that the school site has been inspected by the Sh.R.C.jain, SDE, Provl. Sub Division No. I, Panchkula & Sh.M.P.Sharma, ASDE on dated 27.11.2017. Concerned SDE & ASDE during the inspection has observed that the structure is a RCC framed structure but the structural design of the building was not available. After physical inspection it was observed that the condition of the building looks good. During inspection with respect to stability of structure was observed that no deterioration was found. No cracks in beam, columns were visible. Minor repair in floor tiles were found which is a part of routine maintenance having no relevance with the stability of the structure.

He is further reported that over all the structure of the building seems quite safe as no cracks in column/beams/ slabs etc.

This is for your information and necessary action.

Executive Engineer,
Provl. Divn.Hr. P.W.D B&R,
Panchkula.

Endst No.

Dated:

A copy of above is forwarded to SDE PSD-I, w.r.t. his memo no. 1703 dated 28.11.2017.

DA/Nil

Executive Engineer,
Provl. Divn.Hr. P.W.D B&R,
Panchkula.